




CADDIS


Analog Input Wiring Instructions

ANALOG MACHINE SENSOR



BROWN (PIN 1)
10 VDC SIGNAL
BLACK (PIN 4)
GROUND

24 VOLT DC
POWER
SUPPLY



BROWN (PIN 1)
+24 VDC

BLUE (PIN 3)
0 VDC

M12 CONNECTOR

M12 CONNECTOR





RED - DEVICE HAS POWER,
SETUP MODE ON



GREEN - DEVICE HAS POWER,
SETUP MODE OFF, NETWORK
ESTABLISHED



BLUE (FLASH) - MACHINE
OUTPUT CHANGED



www.lcm2m.com

563.823.6218